


Evaluation of Fire-Exposed Structural Members

- Behavior of common structural building materials under exposure to fires
 - During (elevated temperature) and post fire behavior
 - Concrete, CMU, Wood, and Steel
- General and material specific investigative techniques for assessing structures after a fire
 - Field investigations
 - · Laboratory studies
 - Equipment
- Determine extent and severity of structural damage
- References for guidance on fire damage investigations


WJE


columbian of Fire Francisco Shouth and Manubara




































































Reinforced Concrete Structures Structural Damage? Has the residual strength of the concrete been affected? Is compression strength important? Does concrete has higher strength than required by design? Is the damage at a critical section? How close is reinforcing to the surface? Has the concrete to reinforcing bond been disrupted?























































Steel Structures Investigation Suggested Categorization Category I: "Straight" members that appear unaffected. Confirm slight dimensional changes are within fabrication/erection tolerances or if not, if dimensional variations are OK Category II: Member noticeably deformed but could be heat straightened if deemed economical Clearly beyond typical fabrication tolerance, but may be salvaged with straightening or reinforcing Category III: Severely deformed members May have exceeded temperature that alters material properties; however generally a mute point since typically well beyond repair

