

## **RECALL NOTICE**

R. W. Beckett Corp. Announces a Recall Notice for Firomatic<sup>®</sup> ½" Female Pipe Thread (FPT) Fusible Safety Valve p/n 12130

- **Hazard:** The stem may not travel far enough to properly seat and shut off the flow of fuel if exposed to trip point temperature.
- **Recalled Product:** Firomatic<sup>®</sup> ½" FPT valve p/n 12130 as pictured above is affected. Suspect valves can be identified by the name 'Firomatic' cast into the body of the valve.
- **Remedy:** Option 1 Retrofit valve with retrofit kit part number 12130VR. 3½" of clearance above the top of the valve stem will be required. Option 2 – Replace valve or install an additional 12130 valve downstream of existing valve. Manual shut-off of existing valves is not affected.

## For more information: **1-800-645-2876**

www.beckettcorp.com

## This recall is being conducted in cooperation with the U.S. Consumer Product Safety Commission.

Post until 4/1/2017