

Certificate of Analysis  
**PLM Asbestos Identification**

tel - 408-889-5227  
 free - 833-452-5227  
 SJLab@patriotlab.com  
 2186 Paragon Drive, San Jose, CA 95131



Asbestos Sampling.Com  
 IST Risk Management  
 Unit 26 East Terrace Buisness Park  
 Euxton Lane, Charley, PR7 6TE

Report Number: 930488  
 Project Number: W87627  
 Project Name:  
 Project Location: Holmes, NY 12531

Date Collected: 9/3/2022  
 Date Received: 9/7/2022  
 Date Analyzed: 9/8/2022  
 Date Reported: 9/8/2022

Collected By:  
 Claim Number:  
 PO Number:  
 Number of Samples: 2

Lab/Client ID/Layer	Location	Material Description	Color	Composition (%)
930488-001 1	Living Room Wall	Kraft Paper from Aluminum Insulation	Green	98% Cellulose 2% Non-Fibrous Material

**Total Asbestos None Detected**

930488-002 2	Living Room Wall Door	Asphalt Paper Facing for Fiber Insulation	Black	85% Cellulose 15% Non-Fibrous Material
-----------------	-----------------------	---	-------	---

**Total Asbestos None Detected**

*Sharon Craig*

Sharon Craig - Analyst

*Esmeralda Jimenez*

Esmeralda Jimenez - Approved By

Bulk sample(s) submitted was (were) analyzed in accordance with the procedure outlined in the US Federal Register 40 CFR 763, Subpart F, Appendix A; EPA-600/R-93/116 (Method for Determination of Asbestos in Building Materials), and EPA-600/M4-82-020 (US EPA Interim Method for the Determination of Asbestos in Bulk Insulation Samples). Samples were analyzed using Calibrated Visual Estimations (CVES); therefore, results may not be reliable for samples of low asbestos concentration levels. Samples of wall systems containing discrete and separable layers are analyzed separately and reported as composite unless specifically requested by the customer to report analytical results for individual layers. This report applies only to the items tested. Results are representative of the samples submitted and may not represent the entire material from which the samples were collected. "None Detected" means that no asbestos was observed in the sample. "<1%" (less than one percent) or Trace means that asbestos was observed in the sample but the concentration is below the quantifiable level of 1%. This report was issued by a NIST/NVLAP (Lab Code 201022-0) and CADOHS-ELAP (Cert. No. 2900) accredited laboratory and may not be reproduced, except in full without the expressed written consent of Patriot Environmental Laboratory Services, Inc. This report may not be used to claim product certification, approval or endorsement by NIST, NVLAP, ELAP or any government agency.

ASB\_Rep\_8.14



Samples continued...

930488

6		
7		
8		
9		
10		

**Please note, that if the kit is not registered we will NOT process your sample. Please refer to Step 1 of the instructions prior to returning your sample.**

**I confirm that I have read, understood and followed the instructions provided**

Name: \_\_\_\_\_

Signed \_\_\_\_\_

Date: Sep 3 '22

---

**Lab Use Only**

Received by: 

Report Number:

9-7-22 10:00a